

床型 / BED TYPE

ZERO 4000



www.zayer.com

工作尺寸 / WORKING DIMENSIONS

工作台面 Table surface	4.000 x 1.000	
纵向行程 Longitudinal travel	4.000	mm
横向行程 Cross travel	1.200	mm
垂直向行程 Vertical travel	1.600	mm

直线轴承载力 / CAPACITY OF LINEAR AXIS

快速进给 Rapid feed	40.000	mm/min
工作进给 Working feed	35.000	mm/min
驱动 / Drives:		
. 纵轴 . Longitudinal axis	滚珠丝杠 / Ball screw	
. 横轴 . Cross axis	滚珠丝杠 / Ball screw	
. 垂直轴 . Vertical axis	滚珠丝杠 / Ball screw	

CNC

MITSUBISHI M830W + WHDW



头 HEAD

45°, 360.000 个位置 0.001 分度 / positions

功率
Power 30 kW

主轴头速度
Speed of the spindle head 8000 min⁻¹



附件 EQUIPMENT

刀库 / Tool magazine 40

冷却设备
Coolant equipment 22 + 5 bar

排屑器 2 个纵向鹅颈式+1 个横向鹅颈式
Chip conveyor 2 longitudinal + 1 cross goose neck

刀具测量探头
Tool measurement probe RENISHAW NC4
工件测量探头
Workpiece measurement probe RENISHAW RMP 600

防护 顶部开放的完整防护罩
Protections complete enclosure open on top